


“The Problem Solvers”

Supplying Specifically Designed and Created Problem Solving Solutions.

Problem: Require a Danger or out of Service tag.

Solution: Hi Visibility, tough **Poly Tag Holder P/No 0079**

- 3 compartments for “Danger Tags, Out of service tags etc.
- 2 holes cast in for ease of installation.
- Built to last and withstand underground mining conditions.



PPE to be worn at all times